

Distribution Report

Monthly Report

November 2014

We started November by digging up the pit less unit for #4 well. We also helped Northway install the new pit less unit. We installed new conduit from the well to the well house for the electric lines as well for the air line. Did fall cleanup at our shop, installed snow fence at #7 well house, Pumped out our fall hydrants that won't drain back. We also did vehicle maintenance and ran new silt fence around the sand pile. And did service taps in Authors 3rd addition.

In addition we also did the following

Repair water main leaks: 3

Hydrant maintenance: 1

Hydrants turned: 5

Service taps: 14

Measure new curb boxes: 14

Service orders: 32

Hydrants loaded out: 2

Prepared by Curt Huhndorf