

Distribution Report

Monthly Report

November 2016

Replaced three eight inch valves on dale view dr.

In addition we also did the following

Hydrant maintenance: 2

Hydrants turned: 5

Service taps: 31

Measure new curb boxes: 56

Hydrants loaded out: 7