

# Distribution Report

## Monthly Report

September 2017

We replaced bolts in two twelve inch and one eight inch valve on Lucore Rd. and Silver Oak Trail. One of the twelve inch valves had failed and was leaking do to the bolts being eaten away. Dug up a ten inch valve at 2709 29<sup>th</sup> Ave and replaced bolts and added a valve box. Replaced a curb stop box and stem at Oak Shade cemetery and fixed there water leak.

In addition we also did the following

Fixed water leaks:

- 10<sup>th</sup> Ave and 13<sup>th</sup> St.

Repair valve boxes: 2

Hydrant maintenance: 1

Hydrants turned: 10

Service taps: 31

Measure new curb boxes: 34

Hydrants loaded out: 12