

Distribution Report

Monthly Report

March 2018

We installed the new water line from well ten and ran it to the existing well line to the ground storage tank. We also installed piping for the check valve and meter for well ten. This also involved digging up the well head for Northway Well and Pump to install the pitless unit.

In addition we also did the following

Repair water leak

- 980 West 14th St

Hydrant maintenance: 2

Hydrants turned: 2

Service taps: 83

Measure new curb boxes: 61

Hydrants loaded out: 9