

Distribution Report

Monthly Report

September 2015

Finished 10th ave main project. Dug up and replaced leaking hydrant at 100 35th St. Dug up leaking valve at Munier Rd. and 35th St. we also fixed one water leak.

In addition we also did the following

Fixed water leak

- 200 35th St.

Leak holes repaired: 2

Hydrant maintenance: 1

Hydrants turned: 1

Service taps: 30

Hydrants loaded out: 4