

Distribution Report

Monthly Report

December 2025

Distribution activities: Started building our upper deck in the new shop facility

Water leaks repaired

- 1105 Maplecrest Dr.
- Country Club Drive & Maplecrest Dr
- South 6th St & Hillview Dr

In addition, we also did the following

Service taps: 22

Hydrants loaded out: 1