

Distribution Report

Monthly Report

February 2026

Distribution activities: Found service leak at 1038 Rolling Glen Dr. The service was bored through by Imon communications.

In addition, we also did the following:

Repair valve boxes: 1

Service taps: 5

Measure curb boxes: 5

Hydrants loaded out: 2

Leaks repaired:

- 2350 Indian Creek Rd
- 2585 14th Ave
- 3010 19th Ave
- 2190 1st Ave
- 4529 Surrey Ct