

Distribution Report

Monthly Report

October 2016

October started out working at well site six installing one twelve inch and one four inch valve plus sixty feet of four inch water main. We also had Utility Equipment install one eight inch cut in valve on 31st St. and 4th Ave. We repaired/ graded/seeded well sit five yard from the tank repair project. Hauled sand/rock to our shop in preparation for leak season. We also purchased thirty two loads of black dirt and hauled that to our shop for repairing of yards.

In addition we also did the following

Fixed water leak:

- 1805 Daleview Dr.

Repair valve box: 1

Hydrant maintenance: 4

Hydrants turned: 1

Service taps: 19

Measure new curb boxes: 19

Hydrants loaded out: 2