

Distribution Report

Monthly Report

June 2018

We started our 13th St main project. Installed well #10 well meter cabinet and meter.

In addition, we completed the following:

Repair valve boxes: 4

Hydrant maintenance: 9

Hydrants turned: 12

Service taps: 21

Measure new curb boxes: 31

Hydrants loaded out: 11