

Distribution Report

Monthly Report

October 2014

October was a very busy month for us. We dug up the a curb stop box and replaced it at 262 6th Ave for non-pay, dug a box up at 694 7th Ave and shut it off for the new roundabout. We replaced two twelve inch valves at well #4 plant and dug up another to remove it. Installed conduit at #9 well to go to well house #6, also poured concrete at well #6. Flushed 35th St main project, mowed and did vehicle maintenance. We hauled sand and rock to are shop stock pile for winter leak season.

In addition we also did the following

Repair valve boxes: 2

Hydrant maintenance: 1

Hydrants turned: 18

Service taps: 12

Measure new curb boxes: 15

Service orders: 1

Locates: 38

Prepared by Curt Huhndorf