

# Distribution Report

## Monthly Report

July 2018

We worked on 13<sup>th</sup> St main project

In addition, we did the following:

Repair valve boxes: 1

Hydrant maintenance: 3

Service taps: 36

Boxes measured: 36

Hydrants loaded out: 8