

# Distribution Report

## Monthly Report

September 2018

September involved disconnecting the six-inch water main from the twelve-inch main in the continuation of the 8<sup>th</sup> Ave main abandonment. We also replaced one broken four-inch main valve at 8<sup>th</sup> Ave and 12<sup>th</sup> St. We also finished yard work on 13<sup>th</sup> St. and started yard work at well site #7

In addition, we also did the following

Hydrants turned: 3

Service taps: 2

Measure curb boxes: 27

Hydrants loaded out: 1