

Distribution Report

Monthly Report

June 2019

We did the new main install at our shop, removed the meter pit to above ground. Started our 10th Ave main project.

In addition, we also did the following

Repair valve boxes: 2

Hydrant maintenance: 2

Hydrants turned: 1

Hydrants loaded out: 5